## Nº 11020 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-12-00	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2310	
SIZE OF PIPE USED_6	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB? 755	-11 J. C.
WAS ATTACHED TO MAIN 25	NAME OF CONTRACTOR Malacetes The
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
	7/6 7/10 AFF N
SIGNED BELL CONTROL Inspector for City	FILED AT ENGINEER'S OFFICE

## $N^{0}$ 11020

## OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

MASSILLON, OHIO, 3//1
RECEIVED OF DISTURBILLED ASSURED OF \$ 5
OR WHICH PERMISSION IS GRANTED WALLELE
O TAP SEWER ON THE SEWER ON THE
FARE TYPE OF STREET CAPABLE
HE PREMISES BEING LOT NO. 15911, HOUSE NO. 2310
ORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND F THE DEPARTMENT OF PUBLIC SERVICE.
AME OF CONTRACTOR ALLENGUE ALL HOMES

Note: This permit covers work outside of building only. Any wor walls of building is subject to Massillon Board of Health Regulations.