Nº 11045 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 6-2.60 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |
|--|--|
| HOUSE NO. 2365 | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| WAS LATERAL AT CURB? YES | $\mathcal{A} = \mathcal{A} $ |
| WAS ATTACHED TO MAIN_ 755 5 | NAME OF CONTRACTOR |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WAL | L OF BUILDING SERVED. |
| e de la companya de | |
| and the state of t | LA-1-17-1/ 1/4 |
| en de la companya de La companya de la co | 220 25' |
| | 22° |
| Λ | en e |
| SIGNED RISPEPTOR FOR City | FILED AT ENGINEER'S OFFICE |
| | and the company of th |
| REMARKS | |

Nº 11045

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

| | | MASSILLON, OHIO | 4//8 |
|-------|--|----------------------------|---------------------------------|
| | RECEIVED OF | MASSILLON, ONIO | FEE OF \$.2 |
| ار پا | FOR WHICH PERMISSION IS GRANTED | Marat | · |
| | TO TAP A A A A A A A A A A A A A A A A A A | SEWER ON THE | South |
| | or februle Boach | AVE. ST. TYPE OF STREET | dephale |
| | THE PREMISES BEING LOT NO. | , LC, HOU | ISE NO. 3361 |
| | WORK TO BE DONE IN ACCORDANCE WITH OR | IDINANCE NO. 19-1971 DULY | PASSED BY THE CITY COUNCIL, AND |
| | OF THE DEPARTMENT OF PUBLIC SERVICE. | | |
| | NAME OF CONTRACTOR | UN | |

Note: This permit covers work outside of building only. Any wor walls of building is subject to Massillon Board of Health Regulations.