Nº 11046

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-2.60	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2375		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? YR 5		
WAS ATTACHED TO MAIN 7/5	NAME OF CONTRACTOR Tout	
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.	
	15' Nd	
SIGNED BULL Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS		

Nº 11046

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	4/18
RECEIVED OF	1 aust	FEE OF \$ 57
FOR WHICH PERMISSION IS GRANTED	40425	
TO TAP	SEWER ON THE	<u> </u>
OF COULT GOOD ST.	TYPE OF STREET AND A	<u> </u>
THE PREMISES BEING LOT NO.) , HOUSE NO	23.75
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	E NO. 19-1971 DULY PASSED BY TH	E CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR / 11/14/14	4	, X

Note: This permit covers work outside of building only. Any wor walls of building is subject to Massillon Board of Health Regulations.