Nº 11062

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

_	\mathcal{I}
DATE INSPECTED 5-24-00	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2765	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	NAME OF CONTRACTOR BONTENGE Che
WAS ATTACHED TO MAIN 4	NAME OF CONTRACTOR ON CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	5'4 [] 5'4 [] 5'4 [] 8'psep 30'
SIGNED But Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SE

Nº 11062

H21383 PERMIT TO TAP SEWER

	MASSILLON, OHIO,
RECEIVED OF	Angle
FOR WHICH PERMISSION IS GRANTED	
то тар	SEWER ON THE
of 600 C Ab	AVE. ST. TYPE OF STREET
THE PREMISES BEING LOT NO. $\frac{7775}{1000000000000000000000000000000000000$, House No
WORK TO BE DONE IN ACCORDANCE WITH ORDINA	NCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.	,
NAME OF CONTRACTOR	And -
Note: This permit covers w	ork outside of building only. Any wor

walls of building is subject to Massillon Board of Health Regulations.