

Nº 11076

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/7/00

IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM 4'

HOUSE NO. 330

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Tissot

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature]  
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11076

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, \_\_\_\_\_

6/7, 20\_\_

RECEIVED OF \_\_\_\_\_

*Tessat*

FEE OF \$ \_\_\_\_\_

5

FOR WHICH PERMISSION IS GRANTED \_\_\_\_\_

REPAIR  
TO TAP  
CUTOFF

*Sanitary*

SEWER ON THE \_\_\_\_\_

*# East*

OF \_\_\_\_\_

*Stuebner*

AVE.

ST. TYPE OF STREET. \_\_\_\_\_

*residential*

THE PREMISES BEING LOT NO. \_\_\_\_\_

*15141*

HOUSE NO. \_\_\_\_\_

*330*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR \_\_\_\_\_

*Tessat*

**Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.**