


Nº 11079

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-12-00 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 242'
HOUSE NO. 320
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? YES
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Tissot
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Jeffrey M King Inspector for City 242'
8" FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 11079

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/12, 20

RECEIVED OF Inest FEE OF \$ 57

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP Sanitary SEWER ON THE Duct S
CUTOFF

OF Apple Pl AVE. ST TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 15187, HOUSE NO. 320

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Inest

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**