

Nº 11096

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-22-00

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1800

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Bontaga Inc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11096

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

AK # 21415

MASSILLON, OHIO, 7/2/20

RECEIVED OF Bontugan FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP Sanitary SEWER ON THE East S
CUTOFF

OF John Carroll St AVE. Asphalt
ST TYPE OF STREET

THE PREMISES BEING LOT NO. 10975, HOUSE NO. 11500

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Efficient Homes

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.