

Nº 11097

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-21-00

IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1810

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH


SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Bontinger Etc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill P.

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

No 11097

UR # 21415

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

# PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/20, 20

RECEIVED OF Bartughe FEE OF \$ 52

FOR WHICH PERMISSION IS GRANTED

REPAIR TO TAP Sanitary SEWER ON THE West S  
CUTOFF

OF John Carroll Dr AVE. ST. TYPE OF STREET 192nd St

THE PREMISES BEING LOT NO. 10976, HOUSE NO. 1810

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Efficient Homes

**Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.**