		•	-		-
$N_{\overline{0}}$	1	1	1	0	9

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH  WAS LATERAL AT CURB? NAME OF CONTRACTOR  SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.  SIGNED FILED AT ENGINEER'S OFFICE	HOUSE NO.	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM				
WAS ATTACHED TO MAINNAME OF CONTRACTORSHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.  SIGNEDFILED AT ENGINEER'S OFFICE	SIZE OF PIPE USED	DOWN STREAM TO DITCH AT				
SIGNED FILED AT ENGINEER'S OFFICE	WAS ATTACHED TO MAIN	NAME OF CONTRACTOR				
		FILED AT ENGINEER'S OFFICE				

## $N^{0}$ 11109

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	A . MASSILLON, OHI	IO,	5/,20
RECEIVED OF	Lust	FEE OF 8	s57
FOR WHICH PERMISSION IS GRANTED	TT-TT-TT-TT-TT-TT-TT-TT-TT-TT-TT-TT-TT-		
THE PREMISES BEING LOT NO.	SEWER ON THE	OUSE NO.	s s
/ WORK TO BE DONE IN ACCORDANCE WITH ORDINAN	NCE NO. 19.1971 DULY PASSED	BY THE CITY COUNCIL, AND	RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	127		
NAME OF CONTRACTOR	S. 1821 1	NAMES OF THE PARTY	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.