

N^o 11110

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-28-00

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

115'

HOUSE NO. 1717

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Elisch

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.


Lateral cut-off 12'
of main. 6' North
of Tree South

5' wide $\pm$ Walk

115'



MOHICAN AVE SE
Arapahoe S.E.



SIGNED _____
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11110

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, August 16, 20

RECEIVED OF Elisch FEE OF \$ 15

FOR WHICH PERMISSION IS GRANTED Sanitary

REPAIR TO TAP Sanitary SEWER ON THE South East S

CUTOFF OF Mohican S. E AVE. ST. TYPE OF STREET Concrete

THE PREMISES BEING LOT NO. 12771, HOUSE NO. 1717

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Elisch

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.