## Nº 11117

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $8-25-00$ HOUSE NO. $2920$ SIZE OF PIPE USED $6''$ WAS LATERAL AT CURB? $75$	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR BOUGH MAN
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	UILDING SERVED.
	3772 Srivery ————————————————————————————————————
	770
SIGNED Min M Min) Unspector for City	G14∰
REMARKS	

## Nº 11117

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO FOR WHICH PERMISSION IS GRANTED REPAIR SEWER ON THE TO TAP THE PREMISES BEING LOT NO. WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19,1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE. NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.