


Nº 11124

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-5-00 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. 528
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? YES
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Isot Etc.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Pappas FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11124

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

9/5, 20

RECEIVED OF _____

Gissent

FEE OF \$ _____

57

E

FOR WHICH PERMISSION IS GRANTED _____

REPAIR

TO TAP

CUTOFF

Sanitary

SEWER ON THE _____

East

S

OF _____

Kingman St

AVE.

ST. TYPE OF STREET _____

asphalt

THE PREMISES BEING LOT NO. _____

11623

, HOUSE NO. _____

528

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Gissent / Spacher

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.