N^{0} $1\overline{1}\overline{1}2\overline{5}$

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-11-0 0 HOUSE NO. 13.37 SIZE OF PIPE USED WAS LATERAL AT CURB? 15 5 WAS ATTACHED TO MAIN 45 5	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	ILDING SERVED.
	34' Proprety line Jackson Ave Road
SIGNED Bill () Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

 N° 11125

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

u)	RECEIVED OF	Evit (MASSILLON,	ОНЮ,	FEE OF \$	9/7.20_
	REPAIR TO TAP CUTOFE OF	(/ Ave.)	VER ON THE		agehi	ut Lt
	THE PREMISES BEING LOT NO.			, HOUSE NO		337
	WORK TO BE DONE IN ACCORDANCE W DEPARTMENT OF PUBLIC SERVICE.	/ITH ORDINANCE NO. 19	9.1971 DULY PAS	SED BY THE CI	TY COUNCIL, AND F	RULES OF THE
	NAME OF CONTRACTOR	End C	· ()		<u> </u>	:

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.