

N^o 11126

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED


DATE INSPECTED 10/23/00 IF SO, HOW AND LOCATION FROM 115'
FIRST MANHOLE DOWN STREAM

HOUSE NO. 420 DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
SIZE OF PIPE USED 6" CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Exit C&D

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature] Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11126

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

9/7

, 20 _____

RECEIVED OF _____

FEE OF \$ _____

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

OF _____

ON THE _____

AVE.

ST. TYPE OF STREET _____

THE PREMISES BEING LOT NO. _____

HOUSE NO. _____

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**