Nº 11128

REMARKS \_\_\_\_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	10/23/00	_ IF SO, HOW AND LOCATION FROM	52'				
HOUSE NO	425	FIRST MANHOLE DOWN STREAM					
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT					
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH					
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Exit C&D				
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.							
SIGNED AT ENGINEER'S OFFICE							
· ( )	/ Inspector for City						

44= 6

## Nº 11128

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF	End	MASSILLON, OHIO,	9/.36_ FEE OF \$
FOR WHICH PERMISSION IS GRANTED	www.aanwaranna		
REPAIR TO TAP CUTOFF	X	VER ON THE	west
OF Child	AVE. ST. TYI	PE OF STREET	andalt
THE PREMISES BEING LOT NO.	Studen	Ligge, House No	425
WORK TO BE DONE IN ACCORDANCE WITH	1 ORDINANCE NO. 19	9.1971 DULY PASSED BY THE	CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.		1	
NAME OF CONTRACTOR	Zul	( ) D	: 

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.