	-	_	-		-
$M_{f ar o}$	1	1	1	2	Ç

REMARKS

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	10/23/00	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	2.5′	
HOUSE NO.	505′		LiJ	_
SIZE OF PIPE USED	6 "	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT		
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH		
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Exit C&D	
SHOW BY DIAGRAM RELATIO	N OF LATERAL TO WALL OF	BUILDING SERVED.		
SIGNED Johly M	Inspector for City	2.5' 2.5' FILED AT ENGINEER'S OFFICE	Z.>	

Nº 11129

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	RECEIVED OF X + C	SILLON, OHIO,FEE	9/7 ₂₀ _
ł	FOR WHICH PERMISSION IS GRANTED		
\ -	REPAIR TO TAP	HE INCOME	£
,~ L	CUTOFF AVE.		1
	OF	REET A A A	halt_
	THE PREMISES BEING LOT NO. AUGO WILLS	. / L./LQ_HOUSE NO	505
VS/	<i>y</i>		
0	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DU	LY PASSED BY THE CITY COUNCIL, A	AND RULES OF THE
, }	DEPARTMENT OF PUBLIC SERVICE.	. 1	
D T	NAME OF CONTRACTOR	& D	•

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.

1.12ªT