## $N^{\circ}$ $1\dot{1}\dot{1}\dot{4}\dot{5}$

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. 350  SIZE OF PIPE USED 67	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?	$\Lambda$ $\iota$ $\Omega$		
WAS ATTACHED TO MAIN 49 5	NAME OF CONTRACTOR Jengel The		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
SIGNED	10 AB3   10 EFP   11 - 220   11 - 220   11 - 220   11 - 220   11 - 220   12 - 200   12 -		
Inspector for City			
REMARKS			

Nº 11145

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	∩ MASSILLON,	OHIO	9/20_
RECEIVED OF	Johnys Ex	austing FEE OF	s
REPAIR 10 TAP	SEWER ON THE	Morat	t.
OF Staut Wu	AVE.	MANAA	<u> </u>
THE PREMISES BEING LOT NO.	2 1 Treat	, HOUSE NO.	10
WORK TO BE DONE IN ACCORDANCE W	/ ITH ORDINANCE NO. 19.1971 DULY PASI	SED BY THE CITY COUNCIL, AND	RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR	Jerrell Belg	,	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.