## Nº 11149

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO.				
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH			
WAS LATERAL AT CURB?				
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	FILED AT ENGINEER'S OFFICE			
Inspecto	r for City			
PEMARKS				

## Nº 11149

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

atro	FOR WHICH PERMISSION IS GRANTED  REPAIR TO TAP CUTOFF  MASSILLO  MASSILLO  SEWER ON THE	ON, OHIO,	9/25,20 FEE OF \$ 3]
	OF	, HOUSE NO	TXWASH 522
traffly	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY P DEPARTMENT OF PUBLIC SERVICE, NAME OF CONTRACTOR	PASSED BY THE CIT	Y COUNCIL, AND HULES OF THE

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.