N^{o} 11150

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM			
HOUSE NO	FIRST MANHOLE DOWN STREAM			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB? YE 5 WAS ATTACHED TO MAIN YE 5	() () ()			
, , , , , , , , , , , , , , , , , , , ,	NAME OF CONTRACTOR			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	71 DEEP 30'			
Bill F	91055			
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE			
REMARKS				

Nº 11150

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

1	RECEIVED OF JULY 1	MASSILLON, OHIO, ————————————————————————————————————	9/24 .20 FEE OF \$ 5
<i>.</i>	TO TAP SEN	WER ON THE	iest inplant
	THE PREMISES BEING LOT NO	, HOUSE NO	1/75
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO., 1 DEPARTMENT OF PUBLIC SERVICE.	19.1971 DULY PASSED BY THE CITY	COUNCIL, AND RULES OF THE

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.