

N^o 11158

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-11-00

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 641

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill Rogers
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11158

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/10, 20

RECEIVED OF _____ FEE OF \$ _____ 50

FOR WHICH PERMISSION IS GRANTED John's Excavating

TO REPAIR TAP top sanitary SEWER ON THE west S

OF Wayne St AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 1518, HOUSE NO. 661

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR John's Excavating

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.