FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	10/16/00	IF SO, HOW AND LOCATION FROM	145'			
HOUSE NO.	2665	FIRST MANHOLE DOWN STREAM	173			
SIZE OF PIPE USED	6*	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH				
WAS LATERAL AT CURB?	yes					
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Tissot			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.						
		Z >	8'dp 190- 8'dp 190- 6'x4' -10' 45' -11' -13' Heasurenents From main are no Use Reasurenents From House. 13'dp -37'	ot (
SIGNED Jaff	M Minspector for City	FILED AT ENGINE	ER'S OFFICE			
REMARKS	· · · · · · · · · · · · · · · · · · ·					

 $N^{\underline{0}}$ 11162

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF	MASSILLON, O	7	/()//(20_ FEE OF \$
FOR WHICH PERMISSION IS GRANTED			
TOR WHICH PERINGSION IS GRANTED			
TO TAP SE	EWER ON THE	we	Let
OF SAME GARAGE STREET	ÝPE OF STREET	asp	Last
THE PREMISES BEING LOTAO.		/ HOUSE NO	1665
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. DEPARTMENT OF PUBLIC SERVICE.	19.1971 DULY PASSE	ED BY THE CITY COUNC	CIL, AND RULES OF THE
NAME OF CONTRACTOR/\(\text{ULLess}\)			•

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.