Nº 11164

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	10/19/00	_ IF SO, HOW AND LOCATION FROM 196'			
HOUSE NO.	1895	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT			
SIZE OF PIPE USED	6"				
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH			
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR			
SHOW BY DIAGRAM RELATION	OF LATERAL TO WALL OF	BUILDING SERVED. 1895 Case Vestern 90°-6- 22°20' 22°46' 196'			
SIGNED JAMEN	Inspector for City	FILED AT ENGINEER'S OFFICE			

Nº 11164

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		MASSILLON, OHIO,		101/208
ل	LL RECEIVED OF WALL	te	FEE O	Fs
8	FOR WHICH PERMISSION IS GRANTED			
68	CUTOFE	ON THE	CLKINA SENO.	1891
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.193 DEPARTMENT OF PUBLIC SERVICE.	'1 DULY PASSED B'	Y THE CITY COUNCIL, AN	D RULES OF THE
	NAME OF CONTRACTOR	Frul		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.