

Nº 11167

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-25-00 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____


HOUSE NO. 12

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Daniels Etc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED B. J. Pappas Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11167

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/14/20

RECEIVED OF DeFector FEE OF \$ 15

FOR WHICH PERMISSION IS GRANTED

REPAIR TO TAP CUTOFF Sewerage SEWER ON THE East S

OF Mississippi Ave. ST. TYPE OF STREET Right of Way

THE PREMISES BEING LOT NO. 609, HOUSE NO. 12

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Burger King

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.