

Nº 11172

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 11-14-00 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____


HOUSE NO. 1945

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR Bonstegen Inc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill [Signature] FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

N^o 11172

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/31 201

RECEIVED OF Bontanger

FEE OF \$ 52

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

SEWER ON THE West

SI

OF Carrollton Ave.

AVE.

ST. TYPE OF STREET Highway

THE PREMISES BEING LOT NO. 11965

HOUSE NO. 1945

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Effluent Homes

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**