REMARKS _____

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO	DATE INSPECTED	12/6/00	IF SO, HOW AND LOCATION FROM 140'				
WAS ATTACHED TO MAIN WAS ATTACHED TO MAIN WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR Buckeye NAME OF CONTRACTOR SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. 132 Chestnut NE 132 Chestnut NE 133 Chestnut NE 134 Chestnut NE	HOUSE NO.	132	FIRST MANHOLE DOWN STREAM				
WAS LATERAL AT CURB? WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR Buckeye NAME OF CONTRACTOR SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. 110' 132 Chestnut NE 26 132 Chestnut NE 26 133 Chestnut NE	SIZE OF PIPE USED	6"					
WAS ATTACHED TO MAIN		No					
75' N of west side of the step. 132 Chestnut NE 26' Lateral cut-off 4'dp		yes	NAME OF CONTRACTORBuckeye				
75' N of west side of the step. 75' N of west side of the step. 132 Chestnut NE	SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.						
SIGNED JAM M FILED AT ENGINEER'S OFFICE							

Nº 11179

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

/	MASSILLON	I, OHIO,	11/13,20_
RECEIVED OF	uckeye	· · · · · · · · · · · · · · · · · · ·	FEE OF \$
FOR WHICH PERMISSION IS GRANTED			
REPAIR TO TAP	SEWER ON THE _	100	hada.
ог Ситогр	AVE. STOYBE OF STREET		S. K. O. C.
THE PREMISES BEING LOT NO.		<i>f</i>	132
WORK TO BE DONE IN ACCORDANCE WITH	I ORDINANCE NO. 19.1971 DULY PA	SSED BY THE CITY CO	OUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	Andrew Company		
NAME OF CONTRACTOR	MCNes y	. Land Water Market Water Transport	
Note: This permit co	vers work outside of l	ouilding only.	Any work inside

walls of building is subject to Massillon Board of Health regulations.