


N^o 11182

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-30-00 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM Go into MH
HOUSE NO. 2910
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? No
WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR Malventi Eng.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bice FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11182

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/28, 20

RECEIVED OF Malone FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED

REPAIR TO TAP Sanctuary SEWER ON THE South SIDE
CUTOFF

OF Washington Blvd AVE. ST. TYPE OF STREET Ward

THE PREMISES BEING LOT NO. , HOUSE NO. 2910

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19,1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malone

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.