

N^o 11185

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12-14-00

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2655

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Bontrager Etc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED B. J. [Signature]
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11185

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/06/06

RECEIVED OF Efficient Homes FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED Bontrager Excavating

REPAIR
TO TAP tap sanitary SEWER ON THE south SI
CUTOFF

OF Linda Lane SW AVE.
ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 16046 (55) HOUSE NO. 02655

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Bontrager

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**