

N^o 11187

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-31-00

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1320 1315P

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Malawita Etc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

B. J. O. P.
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11187

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/06/00, 2000

RECEIVED OF Efficient Homes FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED Portager Excavating

REPAIR TO TAP for utility SEWER ON THE East SIDE
CUTOFF

OF Amelia St AVE.
ST. TYPE OF STREET public

THE PREMISES BEING LOT NO. 16045 (57), HOUSE NO. 1520
1315

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Portager

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.