Nº 11197

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	1/19/01	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	150'		
HOUSE NO.	515		137		
SIZE OF PIPE USED	6*				
WAS LATERAL AT CURB?	yes		·		
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Exit C&D		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.					
_	5.5'dp /	teral cut-off 8.75' behind c 159'	turb.		
1	5	1st NW	/ 6		
SIGNED JAMES W	Inspector for City	FILED AT ENGINEER'S	OFFICE		
DEMARKS					

Nº 11197

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MAȘSILLON, OHIO, —	, 20 <u>/</u>
RECEIVED OF	Euch CfD	FEE OF \$
FOR WHICH PERMISSION IS GRANTE	ED	
REPAIR TO TAP	SEWER ON THE	a. L. F
CUTOFF DF	AVE.	
THE PREMISES BEING LOT NO	, House	No
	E WITH ORDINANCE NO. 19.1971 DULY PASSED BY T	HE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE. NAME OF CONTRACTOR	Ent CD	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.