•	-	•	-	_
1	1	1	9	9

 $N_{\bar{0}}$

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	DATE INSPECTED	- 1/18/01	F SO, HOW AND LOCATION FROM	
	HOUSE NO.	113	FIRST MANHOLE DOWN STREAM 72'	· · · · · · · · · · · · · · · · · · ·
. s	SIZE OF PIPE USED	6*	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
	WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH	
	WAS ATTACHED TO MAIN _	yes	NAME OF CONTRACTORExit C&D	
	SHOW BY DIAGRAM RELATION	ON OF LATERAL TO WALL OF	BUILDING SERVED.	
٠		<u> </u>	cut-off for 113 Cherry no 6'0p lateral cut-off 72' 8 curb From MHO Intersection Cherry, no	\ \ \
			-	
	SIGNED Joff M	lispector for City	FILED AT ENGINEER'S OFFICE	

Nº 11199

OFFICE OF THE DIRECTOR OF PUBLIC SERVICI PERMIT TO TAP SEWER

RECEIVED OF	MASSILLON, OHIC	o,
FOR WHICH PERMISSION IS GRANTE	ED	
REPAIR TO TAP	SEWER ON THE	
GUTOFF OF	AVE. ST, TKPE OF STREET	and the second
THE PREMISES BEING LOT NO.	1	USE NO//5
WORK TO BE DONE IN ACCORDANG	FINITU ODDINANCE NO. 40 4074 DUNY DACCED	DV THE CITY COUNCIL AND BUILTS OF THE
WORK TO BE DONE IN ACCORDANCE DEPARTMENT OF PUBLIC SERVICE.	E WITH ORDINANCE NO. 19.1971 DULY PASSED	BY THE CITY COUNCIL, AND HULES OF THE
NAME OF CONTRACTOR	Emit Clb	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.