## Nº 11205

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-2-5/ HOUSE NO. 239	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	NAME OF CONTRACTOR CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	UILDING SERVED.
	Soften X
	CURB AT ROAD
SIGNED Bill Signed Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 11205

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF	MASSILLON, Cardhiel	OHIO,FEE OF	
FOR WHICH PERMISSION IS GRANTED			
REPAIR TO TAP CUTOFF	Lucies EWER ON THE	Mex	<u>t</u>
OF MANGE	AVE.	dagde	14
THE PREMISES BEING LOT NO.	9754	., HOUSE NO.	39
WORK TO BE DONE IN ACCORDANCE WITH C	PRDINANCE NO. 19.1971 DULY PAS	SED BY THE CITY COUNCIL, AND	) RULES OF THE
NAME OF CONTRACTOR	settiell_		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.