

Nº 11212

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-13-01

IF SO, HOW AND LOCATION FROM

HOUSE NO. 2399

FIRST MANHOLE DOWN STREAM

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH

WAS LATERAL AT CURB? YAS


WAS ATTACHED TO MAIN YAS

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Bonatrugen Epc.

PN



SIGNED Bio P. [Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11212

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 02/15/01, 20__

RECEIVED OF Efficient Homes FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED Bontrager Excavating

REPAIR TO TAP CUTOFF tap sanitary SEWER ON THE south S

OF Malone Ave SE AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 16079 (156), HOUSE NO. 2399

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Bontrager Exc.

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.