N^{0} 11215

REMARKS _____

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM				
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH				
WAS LATERAL AT CURB?	0 + 1				
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR				
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.					
₹ N	2 47 GOTTP CURB				
SIGNED Bullappur	אנע (סף אינע (ס ' 3' (' 'S' ')' 3' (' 'S')' 3' (')' 3' (')' 3' (')' 3' (')' 3' (')' 3' (')' 3' (')' 3				
Inspeator for City					

Nº 11215

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

e e e e e e e e e e e e e e e e e e e	/\	MASSILLON,	оню,	2/26	<u>}</u>
RECEIVED OF	- Cathell) 		FEE OF \$	_
FOR WHICH PERMISSION IS GI	RANTED				
REPAIR TO TAP	Southern SEV	VER ON THE			_
of	LPM (ST. TY	PE OF STREET		agakalt	
THE PREMISES BEING LOT NO	1442		_, HOUSE NO	1123	
	,	/		, ,	
WORK TO BE DONE IN ACCORI	DANCE WITH ORDINANCE NO. 19	9.1971 DULY PAS	SED BY THE CI	ITY COUNCIL, AND RULES OF THI	Ξ
DEPARTMENT OF PUBLIC SERVING NAME OF CONTRACTOR	vice. Cathu	d		_	
	· ·				

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.