Nº 11219

REMARKS ____

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	3/10/01	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	40'	
HOUSE NO.	2950		70	
SIZE OF PIPE USED	6*			
WAS LATERAL AT CURB?	yes			
WAS ATTACHED TO MAIN	yes	. NAME OF CONTRACTOR	Don Glicks Excavating	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. 45° 23' E 2950 Crest Circle BB'				
		8.5'dp -		
SIGNED OF M	Inspector for City	-33' FILED AT ENGINEER'S OF	40' 8'	
SIGNED OUT M	Inspector for City	-33.	8.	

Nº 11219

OFFICE OF THE DIRECTOR OF PUBLIC SERVICI PERMIT TO TAP SEWER

	MASSILLON				
RECEIVED OF	Non Vick	CK Cavationes 5			
FOR WHICH PERMISSION IS GRANTED					
REPAIR TO TAP CUTOFF	SEWER ON THE	MALTA			
of	AVE. LIST. TYPE OF STREET	- anglist			
THE PREMISES BEING LOT NO	A man .	, HOUSE NO			
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.					
NAME OF CONTRACTOR	29 glick				

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.

Tres