N^{0} 11222

REMARKS

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-13-61	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO.	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	C. A
WAS ATTACHED TO MAIN 4/15	NAME OF CONTRACTOR 24 olderson
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED.
	m² 700 - 450
TX	Con demont
	1225+58
SIGNED Biofins	FILED AT ENGINEER'S OFFICE
inspector for City	
•	

Nº 11222

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	-, źo
RECEIVED OF Alderson	FEE OF \$	_5
FOR WHICH PERMISSION IS GRANTED	Walter Centettry	
CUTOFF	ON THE last	
OF CHILD SINGSTRYPE C	OF STREET UND ASIL	
THE PREMISES BEING LOT NO.	, HOUSE NO.	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.197 DEPARTMENT OF PUBLIC SERVICE.	71 DULY PASSED BY THE CITY COUNCIL, AND RULES OF	THE
NAME OF CONTRACTOR Huldling	aun	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.