Nº 11224

REMARKS _____

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	3/26/01	IF SO, HOW AND LOCATION FROM	76'		
HOUSE NO.	2930	FIRST MANHOLE DOWN STREAM	,,,		
SIZE OF PIPE USED	6*	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT			
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH			
WAS ATTACHED TO MAIN _	yes .	NAME OF CONTRACTOR	Tissot		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. 45° 34′ 10′ 5′45°					
		N	45° 15 45° 15 15 15 45° 15 8'dpê house		
SIGNED JAMES W	Inspector for City	G FILED AT ENGINE	33'-/-22°		

Nº 11224

OFFICE OF THE DIRECTOR OF PUBLIC SERVICI PERMIT TO TAP SEWER

4	MASSILLON, OHIO,	3/21/020
RECEIVED OF	<u> </u>	FEE OF \$
WHOR WHICH PERMISSION IS GRANTED	Mussbaune	Charles
	ER ON THE	Ltot h s
OF Yould AVE	E OF STREET	What
THE PREMISES BEING LOT NO	9, HOUSE NO	2930
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19 DEPARTMENT OF PUBLIC SERVICE.	/ .1971 DULY PASSED BY THE CITY COU	NCIL, AND RULES OF THE
NAME OF CONTRACTOR LIST	t januar	e-X

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.