## Nº 11226

REMARKS \_\_\_\_\_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

			•
DATE INSPECTED	3/27/01 325	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	293'
HOUSE NO.	353	<u> </u>	
SIZE OF PIPE USED	6*	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Tissot
SHOW BY DIAGRAM RELATION	OF LATERAL TO WALL O	BUILDING SERVED. 325 Starbrook  B'dpE house 26	≥93' 8'
SIGNED		FILED AT ENGINEER'S	OFFICE
WI NO THE CO.	Inspector for City		

## Nº 11226

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	March 27, 20 0			
RECEIVED OF		FEE OF \$50.c			
FOR WHICH PERMISSION IS GRANTED					
TOTAP Sanitary sev	WERI ON THE	<i>,</i> <del>+</del>			
OF Star brook AVE. ST. TY					
THE PREMISES BEING LOT NO. 15 157		•			
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.					
NAME OF CONTRACTOR TISSOT					

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.