


Nº 11227

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3/29/01 IF SO, HOW AND LOCATION FROM 136'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 2975
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Tissot

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature] FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11227

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/28, 20

RECEIVED OF Lissat FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED J. Kuder

REPAIR TO TAP Sanbury SEWER ON THE South SIDE
CUTOFF

OF Chest Co. Hwy AVE ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 15170, HOUSE NO. 2975

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Lissat

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.