

Nº 11228

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-29-01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2530

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Malone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bert P. Jones
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11228

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/28/01, 20

RECEIVED OF _____ FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED Malavite

REPAIR TO TAP tap sanitary SEWER ON THE North S
CUTOFF

OF Malavite Ave SE AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 16091, HOUSE NO. 2530

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malavite Excavating

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.