


Nº 11229

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-6-01 IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_  
HOUSE NO. 26  
SIZE OF PIPE USED — DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_  
WAS LATERAL AT CURB? YES  
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Buckeye Wrecking  
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bio P... FILED AT ENGINEER'S OFFICE

Inspector for City

REMARKS \_\_\_\_\_

Nº 11229

# OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## PERMIT TO TAP SEWER

MASSILLON, OHIO.

3/28

, 20

RECEIVED OF

FEE OF \$

11

FOR WHICH PERMISSION IS GRANTED

REPAIR  
TO TAP \_\_\_\_  
CUTOFF

SEWER ON THE

5

OF

AVE.

ST\_TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

**Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.**