

N<sup>o</sup> 11242

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

DATE INSPECTED \_\_\_\_\_ IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_

HOUSE NO. \_\_\_\_\_ DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_

SIZE OF PIPE USED \_\_\_\_\_

WAS LATERAL AT CURB? \_\_\_\_\_

WAS ATTACHED TO MAIN \_\_\_\_\_ NAME OF CONTRACTOR \_\_\_\_\_

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

*Permit purchased after work was done.  
No inspection - No information*

SIGNED \_\_\_\_\_ FILED AT ENGINEER'S OFFICE \_\_\_\_\_

Inspector for City

REMARKS \_\_\_\_\_

Nº 11242

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, 4/6 1920

RECEIVED OF

Malavite

FEE OF \$

50

FOR WHICH PERMISSION IS GRANTED

House by Gabley

REPAIR  
TO TAP  
CUTOFF

Sanitary

SEWER ON THE

S

OF

University St

AVE

ST. TYPE OF STREET

Asphalt

THE PREMISES BEING LOT NO.

15291

, HOUSE NO.

2240

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE  
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Malavite

**Note: This permit covers work outside of building only. Any work inside  
walls of building is subject to Massillon Board of Health regulations.**