		_			
Nō	1	1	2	4	

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO.			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	OF BUILDING SERVED.		
No Inspection			
	•		
SIGNED	FILED AT ENGINEER'S OFFICE		
Inspector for City			
REMARKS			

Nº 11243

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

	4/ C/20
A	MASSILLON, OHIO,
D. RECEIVED OF LAULT C	M Cassatuly FEE OF \$
LUFGE WHICH PERMISSION IS GRANTED A	Mattern C
REPAIR	ER ON THE
CUTOFF!	E OF STREET A A A A A A
THE PREMISES BEING LOT NO. 36 768	, HOUSE NO. 2850
w/	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1 DEPARTMENT OF PUBLIC SERVICE.	1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF POBLIC SERVICE.	
NAME OF CONTRACTOR Allaulau	<i>i</i>
7	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.