

Nº 11262

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-1-01

IF SO, HOW AND LOCATION FROM

HOUSE NO. 2580

FIRST MANHOLE DOWN STREAM

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE

WAS LATERAL AT CURB? yes


DOWN STREAM TO DITCH AT

WAS ATTACHED TO MAIN yes

CURB LINE AND DEPTH

NAME OF CONTRACTOR M. B. B. Co.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED B. B. B.
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11262

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/30 2050

RECEIVED OF Malavito

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

SEWER ON THE

OF

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.