


Nº 11263

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED	5/3/01	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	180'
HOUSE NO.	1163	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
SIZE OF PIPE USED	6"		
WAS LATERAL AT CURB?	yes		
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Malavite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

goff on King

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11263

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/3
20

RECEIVED OF M. J. L. L. L.

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

SEWER ON THE

S

OF

AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

, HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. L. L.

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.