		-			
$\Lambda_{\bar{0}}$	1	1	2	6	ϵ

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	·
HOUSE NO.	FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	· ·
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO V	VALL OF BUILDING SERVED.
SIGNEDInspector for C	FILED AT ENGINEER'S OFFICE
mapesior ior o	nty ·
•	
REMARKS	

Nº 11266

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	5/7_,20_
RECEIVED OF WALLS	Te	FEE OF \$
//FØR WHICH PERMISSION IS GRANTED		
REPAIR TO TAP SEW	ER ON THE	Parat
OFAVE.	E OF STREET	post he va-
THE PREMISES BEING LOT NO		/ -
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19 DEPARTMENT OF PUBLIC SERVICE.	1971 DULY PASSED BY THE	CITY COUNCIL, AND RULES OF THE
NAME OF CONTRACTOR Juit	***************************************	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.