


N^o 11273

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/13/01 IF SO, HOW AND LOCATION FROM 116'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1325
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Grabill
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED 116'



SIGNED [Signature] FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11273

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

id, 716
RECEIVED OF Springhill Condo MASSILLON, OHIO, 5/29, 20
FOR WHICH PERMISSION IS GRANTED Shubill FEE OF \$ 56
REPAIR TO TAP Sanitary SEWER ON THE South SIDE
CUTOFF Laurelbrook Lane AVE. OF STREET Depot
OF Laurelbrook Lane THE PREMISES BEING LOT NO. 01 857, HOUSE NO. 1325

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Springhill Condo

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.