


Nº 11274

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/13/01 IF SO, HOW AND LOCATION FROM 130'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1330
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Grabill
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED *Jeffrey M. [Signature]* Inspector for City FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11274

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/29/20

do
71E
RECEIVED OF

Springhill Condo Club #1121 Fee of \$ 50.50

FOR WHICH PERMISSION IS GRANTED

Drainage

REPAIR
TO TAP
CUTOFF

Sanitary SEWER ON THE

north

SI

OF

Laurelbrook Ave

ST. TYPE OF STREET

acp dact

THE PREMISES BEING LOT NO.

00857

, HOUSE NO.

1330

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Springhill Condo

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.