Nº 11284

REMARKS __

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	6/13/01	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	295′	
HOUSE NO.	1380		273	
SIZE OF PIPE USED	6*	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT		
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH		
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Grabill	
SHOW BY DIAGRAM RELATION	OF LATERAL TO WALL OF	BUILDING SERVED.		
			Laurenbrook Lane	
	<u> </u>	295′	c/d c/o 11' w of ne corner	
0 //1	// ₄₀			
SIGNED FOR W	/Inspector for City			
V				

Nº 11284

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/2, 30_	
RECEIVED OF Solution Colors 5	-
FOR WHICH PERMISSION IS GRANTED	
/	-
REPAIR ON THE MOUTH	
OF THUNG IN THE STATE OF STREET WAR ALL	
THE PREMISES BEING LOT NO. 0 (857, HOUSE NO. 1380)	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE	
DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR JULIANUL COULD	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.