


N^o 11289

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5/8/01 IF SO, HOW AND LOCATION FROM 120'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1425
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Grabill
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED *[Signature]* FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11289

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/29
RECEIVED OF Springhill Condo CR 1136 FEE OF \$ 1.50
FOR WHICH PERMISSION IS GRANTED Shirley
REPAIR TO TAP Sanitary SEWER ON THE South SIDE
CUTOFF Burnside St AVE. ST. TYPE OF STREET Asphalt
OF 0C 857 THE PREMISES BEING LOT NO. 1425, HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Springhill Condo

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.