


Nº 11294

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5/8/01 IF SO, HOW AND LOCATION FROM 144'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1450
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH yes
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Grabill
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature] Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11294

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/29, 2020

RECEIVED OF Springhill Condo CL 1134

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED Yard

REPAIR
TO TAP
CUTOFF

SEWER ON THE North SIDE

OF Laurelbrook Dr

AVE.
ST. TYPE OF STREET Residential

THE PREMISES BEING LOT NO. OL 857

, HOUSE NO. 1450

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Springhill Condo

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.